
WIRING INSTRUCTIONS



WIRING SPECIFICATIONS						
Wire No.	Wire Color	Origin or Gauge	Length	Terminals, Connectors and 1 or 2 End Wire Preparation		
1	WHITE	CORD	2-3/4"	STRIP1/4" AND TIN		
2	BLACK	CORD	2-1/4"	STRIP1/4" AND TIN		
3	WHITE	FIELD		STRIP1/4" AND TIN		
4	BLACK	FIELD		STRIP1/4" AND TIN		
5	WHITE	FIELD		STRIP3/16" FOR T1		
6	WHITE	FIELD		STRIP3/16" FOR T1		
7	GREEN	CORD		STRIP3/16" FOR T1		

GREEN (CORD) (7)

NOTE: All leads must be held to $\pm 1/8$ ". All field leads to be measured from and perpendicular to laminations. All lead lengths are before stripping.

TERMINAL DESCRIPTION						
Code	Part No.	Qnty.				
T1	23-74-0840	3				
CONNECTOR DESCRIPTION						