



SERVICE PARTS LIST

BULLETIN NO.
54-26-2990

SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS		REVISED BULLETIN	DATE
M18 FUEL™ 1/4" HEX IMPACT DRIVER			June 2023
CATALOG NO.	2953-20	SERIAL NO.	M67A
		WIRING INSTRUCTION See Pages 3 & 4	





FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.
1	05-92-1010	Retaining Ring	(1)
2	45-88-2026	Washer	(1)
3	40-50-0056	Spring	(1)
4	42-76-0019	Sleeve	(1)
5	40-50-9215	Anvil Spring	(1)
6	45-88-1547	Washer	(1)
10	42-06-7033	1/4" Hex Anvil	(1)
11	02-02-1100	Steel Ball	(2)
22	34-40-0596	O-Ring	(1)
23	-----	Gearcase Cap	(1)
32	06-82-6351	M3 x 16mm Pan Hd. ST T-10 Screw	(9)
33	06-82-2367	M3 x 38mm Pan Hd. ST T-10 Screw	(2)
34	-----	Belt Clip	(1)
35	06-82-2500	6-32 x 7mm Pan Hd. Phillips Mach. Scr.	(2)
36	45-24-8005	Forward/Reverse Shuttle	(1)
40	-----	Right Handle Halve - Cover	(1)
41	-----	Left Handle Halve - Support	(1)
42	12-20-9815	Service Nameplate	(1)
46	-----	Bit Holder	(1)
47	42-55-8995	Blow Molded Carrying Case	(1)
48	49-16-2953	Rubber Boot (Accessory)	(1)
51	14-29-5370	Gearcase/Anvil Svc. Kit w/ Tri-LED Lighting	(1)
52	14-30-2810	Impacting Assembly	(1)
53	44-66-2560	Gearcase Cap Service Kit	(1)
54	14-20-6550	Electronics Assembly	(1)
55	16-01-3045	Rotor/End Cap Service Assembly	(1)
56	14-34-2420	Housing Service Kit	(1)
57	42-70-0950	Belt Clip Service Kit	(1)
58	45-24-2660	Speed Selector Service Assembly	(1)
60	49-16-3697	Bit Holder Kit (Accessory, Optional)	(1)
61	-----	QR Code Label	(1)



Note: QR codes are not user-replaceable. Return your tool to a Milwaukee Authorized Repair Center for QR code replacement.