WIRING INSTRUCTIONS


TITLE

LARGE DRILL POWER UNIT

MILWAUKEE ELECTRIC TOOL CORP.

13135 WEST LISBON RD BROOKFIELD WIS

DATE Mar. '75 BUĽLETIN **58-01-0371**



Refer to electrical parts chart for terminal and connector part nos. and quantity required — see drawing for actual hook-up.

WIRING SPECIFICATIONS											
Wire	Wire Origin or Color Gauge	Origin or		Terminal				Connector			
No.		Length	T1	T2	ТЗ	T4	C1	C2	СЗ	C4	
1	WHITE	CORD	2"								
2	RED	CORD	3-3/4"								
3	BLUE	CORD	3-3/4"								
4	BLACK	CORD	2"								
5	BLACK	FIELD	6-1/2''					X			•
6	YELLOW	FIELD	3-3/4"					×			

All leads must be held to ± 1/8".

All field leads to be measured from and perpendicular to laminations.

All lead lengths are before stripping.

An lead lengths are before stripping.										
ELECTRICAL PARTS										
TERMINAL DESCRIPTION										
Code	ode Part No.									
CONNECTOR DESCRIPTION										
Code	Part No.	Qnty.								
C1	22-56-0160	2								
SWITCH DESCRIPTION										
Code	Part No.	Onty.								